

Photographic Activity Test (Per ISO 18916) Research Report Research Report

Customer: Morten Jacobsen

Dancan Cinema Services, SL Company:

Address: Puerto de Mogan

> 35138 Mogan (NIF B35991231) Las Palmas de GC, Spain

Material: Dancan Plastic Film Can and Core - Black

Silver Image Interaction

Density change of control: -1.27

Upper pass/fail limit: -1.02

Density change of material: -1.14

Lower pass/fail limit: -1.52

Density change caused by material must fall between upper and lower limits (±20% change in control)

Material pass/fail: Pass

Reason: Within image interaction limits

Andrea Venosa

Operator

Note: The PAT should always be used in conjunction with ISO 18902, Imaging Materials - Processed Photographic Films, Plates, and Papers -Filing Enclosures and Storage Containers, when selecting enclosures.

Date: 3/3/15 2260 Job:

Gelatin Staining

Density change of control: 0.11

Stain limit: 0.19

Density change of material: 0.11

Staining caused by material must be less than stain limit (control +0.08)

> Result: Pass

Less than stain limit Reason:

Mottling of Image Interaction Detector

Visual assessment of uniform action

Result: Pass

Overall Performance - Must pass all criteria: **Pass**

This certificate is valid for this specific lot of product until any date. or for any subsequent lot of this product produced until: 3/2/16

This certificate is void upon any change in product formulation, or change in manufacturer or manufacturer suppliers.

Image Permanence Institute, Rochester Institute of Technology, 70 Lomb Memorial Drive, Rochester, NY 14623-5604 - Phone (585) 475-5199 Use and publication of this data is governed by contractual agreement and by RIT's research policy.

^{*} Control material in Whatman No. 1 filter paper



Photographic Activity Test (Per ISO 18916) Research Report Research Report

Customer: Morten Jacobsen

Dancan Cinema Services, SL Company:

Address: Puerto de Mogan

> 35138 Mogan (NIF B35991231) Las Palmas de GC, Spain

Material: Dancan Plastic Film Can and Core - Black Stabilized

Silver Image Interaction

Density change of control: -1.27

Upper pass/fail limit: -1.02

Density change of material: -1.24

Lower pass/fail limit: -1.52

Density change caused by material must fall between upper and lower limits (±20% change in control)

Material pass/fail: Pass

Reason: Within image interaction limits

Andrea Venosa

Operator

Note: The PAT should always be used in conjunction with ISO 18902, Imaging Materials - Processed Photographic Films, Plates, and Papers -Filing Enclosures and Storage Containers, when selecting enclosures.

Date: 3/3/15 2260 Job:

Gelatin Staining

Density change of control: 0.11

Stain limit: 0.19

Density change of material: 0.10

Staining caused by material must be less than stain limit (control +0.08)

> Result: Pass

Less than stain limit Reason:

Mottling of Image Interaction Detector

Visual assessment of uniform action

Result: Pass

Overall Performance - Must pass all criteria: **Pass**

This certificate is valid for this specific lot of product until any date.

or for any subsequent lot of this product produced until:

3/2/16

This certificate is void upon any change in product formulation, or change in manufacturer or manufacturer suppliers.

Image Permanence Institute, Rochester Institute of Technology, 70 Lomb Memorial Drive, Rochester, NY 14623-5604 - Phone (585) 475-5199 Use and publication of this data is governed by contractual agreement and by RIT's research policy.

^{*} Control material in Whatman No. 1 filter paper



Photographic Activity Test (Per ISO 18916) Research Report Research Report

Customer: Morten Jacobsen

Dancan Cinema Services, SL Company:

Address: Puerto de Mogan

> 35138 Mogan (NIF B35991231) Las Palmas de GC, Spain

Material: Dancan Plastic Film Can and Core - Blue Stabilized

Silver Image Interaction

Density change of control: -1.27

Upper pass/fail limit: -1.02

Density change of material: -1.24

Lower pass/fail limit: -1.52

Density change caused by material must fall between upper and lower limits (±20% change in control)

Material pass/fail: Pass

Reason: Within image interaction limits

Andrea Venosa

Operator

Note: The PAT should always be used in conjunction with ISO 18902, Imaging Materials - Processed Photographic Films, Plates, and Papers -Filing Enclosures and Storage Containers, when selecting enclosures.

Date: 3/3/15 2260 Job:

Gelatin Staining

Density change of control: 0.11

Stain limit: 0.19

Density change of material: 0.13

Staining caused by material must be less than stain limit (control +0.08)

> Result: Pass

Less than stain limit Reason:

Mottling of Image Interaction Detector

Visual assessment of uniform action

Result: Pass

Overall Performance - Must pass all criteria:

This certificate is valid for this specific lot of product until any date.

or for any subsequent lot of this product produced until:

3/2/16

Pass

This certificate is void upon any change in product formulation, or change in manufacturer or manufacturer suppliers.

Image Permanence Institute, Rochester Institute of Technology, 70 Lomb Memorial Drive, Rochester, NY 14623-5604 - Phone (585) 475-5199 Use and publication of this data is governed by contractual agreement and by RIT's research policy.

^{*} Control material in Whatman No. 1 filter paper